Photo Survey of 1111 N. Indian Hill Boulevard



Front elevation of the house, Indian Hill Boulevard.



Original window



Entrance to what was formerly Dr. Ilsley's office. Facing Indian Hill Boulevard.



Two-piece clay tile roof. Damage to wooden rafters.



Covered porch in the rear outside the kitchen and dinning room.



Rear Elevation of the house




Close up of second-story windows. The two windows to the right are original windows. The two on the left have been altered, but are included in the applicant's Ten Year Plan to be restored to historic character.



Courtyard. Original doors and windows.



Guesthouse in the rear yard.




Historic oak tree in the rear yard saved by Mrs. Mary Ilsley.



Living room with original features including two arched windows, ceiling beams, fireplace and flooring.



Original corbels installed by Mrs. Mary Ilsley.










Various arched passageways inside the house.





Historic staircase that does not meet current code for height of railing.



Dinning room



Driveway and Living Room Exterior

Pepper Tree

Original Door Screen Off of Living Room to Backyard

Rear Porch, Looking into Living Room

Exterior of Kitchen Window

Backyard, Facing East

Detached Adobe Garage Interior

Backyard with Adobe Walls

Historic Oak Tree

Detached Adobe Garage and Landscape Walls

Bedroom Interior

Guest Bathroom Tile

Hallway From Entry Way to Bedrooms

Casement Window in Kitchen

Casement Window in Bedroom

A Bedroom

Kitchen Cabinetry

Window in Kitchen

Native American Tile Detail Around Fireplace

Living Room

Roof Water Damage From Rain

Ζ

Fireplace in Living Room

Attached Port Cochere and Driveway

Front Entrance

Front Entrance Covered Patio