

**Site Photos**

1. Photos of the applicant's rear yard showing the unpermitted patio cover.







2. Looking towards north from the applicant's rear yard. The northerly neighbor's two inground decks and the Ficus Natida trees planted by the applicants are in the view.



3. Southerly neighbor's rooftop deck, property line fence, and the privacy wall partition built by the applicant as part of the patio construction.



4. The southerly property line fence and the privacy wall partition built by the applicant as part of the patio construction, and partial view of the outdoor kitchen.

