


Photo Survey of 611 West Eighth Street



Driveway, Facing Eighth Street



Garage Exterior



Top of Driveway, Facing Alley, Garage is to the Left



Olive Tree Insect Damage



Olive Tree




Previous Repair Work on Fireplace Exterior



Driveway and Living Room Exterior



Pepper Tree



Original Door Screen Off of Living Room to Backyard



Rear Porch, Looking into Living Room



Exterior of Kitchen Window



Backyard, Facing East



Detached Adobe Garage Interior



Backyard with Adobe Walls



Historic Oak Tree



Detached Adobe Garage and Landscape Walls



Bedroom Interior



Guest Bathroom Tile



Hallway From Entry Way to Bedrooms



Casement Window in Kitchen




Casement Window in Bedroom



A Bedroom



Kitchen Cabinetry




Window in Kitchen



Native American Tile Detail Around Fireplace



Living Room



Roof Water Damage From Rain



Fireplace in Living Room



Attached Port Cochere and Driveway



Front Entrance



Front Entrance Covered Patio