

Photo Survey of 611 West Eighth Street




Driveway, Facing Eighth Street




Garage Exterior



Top of Driveway, Facing Alley, Garage is to the Left




Olive Tree Insect Damage



Olive Tree




Previous Repair Work on Fireplace Exterior




Driveway and Living Room Exterior




Pepper Tree



Original Door Screen Off of Living Room to Backyard




Rear Porch, Looking into Living Room



Exterior of Kitchen Window




Backyard, Facing East



Detached Adobe Garage Interior




Backyard with Adobe Walls



Historic Oak Tree



Detached Adobe Garage and Landscape Walls




Bedroom Interior




Guest Bathroom Tile




Hallway From Entry Way to Bedrooms



Casement Window in Kitchen



Casement Window in Bedroom



A Bedroom




Kitchen Cabinetry




Window in Kitchen



Native American Tile Detail Around Fireplace




Living Room



Roof Water Damage From Rain



Fireplace in Living Room



Attached Port Cochere and Driveway



Front Entrance



Front Entrance Covered Patio