

Photo Survey of 611 West Eighth Street




Driveway, Facing Eighth Street





Garage Exterior





Top of Driveway, Facing Alley, Garage is to the Left





Olive Tree Insect Damage





Olive Tree





Previous Repair Work on Fireplace Exterior






Driveway and Living Room Exterior





Pepper Tree





Original Door Screen Off of Living Room to Backyard





Rear Porch, Looking into Living Room





Exterior of Kitchen Window





Backyard, Facing East





Detached Adobe Garage Interior





Backyard with Adobe Walls





Historic Oak Tree





Detached Adobe Garage and Landscape Walls





Bedroom Interior





Guest Bathroom Tile





Hallway From Entry Way to Bedrooms





Casement Window in Kitchen





Casement Window in Bedroom






A Bedroom





Kitchen Cabinetry





Window in Kitchen






Native American Tile Detail Around Fireplace





Living Room





Roof Water Damage From Rain





Fireplace in Living Room





Attached Port Cochere and Driveway





Front Entrance





Front Entrance Covered Patio